

HEALTH AND SAFETY DATA SHEET

Product no. 2 500 series & 2 600 series	Versio	on 09/98/MW	Status 09/98/M				
Substance code: I. Identification of the substance / pre	nonation and as		Page : 1 (3	5)			
Product details		шрапу					
Trade Name: Alginate Impression N	Material						
Supplier details :							
PSP Dental Company Limited	1						
3-5 Dylan Road	Information provided by:						
Belvedere		PSP Dental Company Limited					
Kent DA17 5QS							
		Emergency telephone number: 020-8311-7337					
		Emergency fax nu	mber: 020 8310	0920			
2. Composition/information on ingre	dients						
Hazardous Compounds:	%	Cas No:	S Phase	R Phase			
Potassium Fluorotitanate	01.05	16919-27-0	22-26-28	25-20/21			
			37/39-44				
Diatomaceous Earth Filler	60-70	68855-54-9	22	40/20			
Non Hazardous Compounds:							
Triethanolamine Alginate	10-20	9005-38-3					
Calcium Sulphate Dihydrate	10-20						
Tetrasodium Pyrophosphate	01-05	7722-88-5					
Magnesium Oxide	01-05						
Sodium Alginate	05-10						
3. Hazards identification							
Unlikely to cause harmful effects		onditions of handling	and use.				
Practice good hygiene. Wear glove	es, overalls.						
4. First aid measures							
After contact with skin:							
Wash immediately with plenty of water							
After contact with eyes:							
Irrigate thoroughly with water for at	least 10 minutes						
After ingestion:							
Wash out mouth with water. Do not	induce vomiting						
After inhalation:	C						
Remove from exposure, rest and kee	p warm						

A:\Alginate Impression Material HSDS.wpd



	oduct no. 2 500 series & 2 600	0 series		Version 01/98/MW	Status 01			
<u>Sul</u> 5.	bstance code: Fire-fighting measures:				Page :	2 (3)		
5.	rnv-ngnung measures.							
	Suitable Extinguishing Me							
	N/A. Product is non-flamma	able						
6.	Accidental release measure	s:						
	Environmental precautions	5						
	Avoid accumulation of dust							
·	Methods for cleaning up / ta Sweep or vacuum. Avoid ge		l damp as it may cause a slip	hazard.				
7.	Handling and storage When handling bulk quantiti Handle in well ventilated are		le protective clothing.					
	Store in a cool dry place. K	Leep container	r lid tightly closed.					
8.	Exposure controls / person	al protection	1					
8.	Exposure controls / person Hygiene measures Remove soiled or soaked clor Wash hands before breaks an	thing immedi	ately.					
8.	Hygiene measures Remove soiled or soaked clo	thing immedi ad after work.	ately.					
8.	Hygiene measuresRemove soiled or soaked clorWash hands before breaks anRespiratory protection: DuHand protection: GluEye protection: Gu	thing immedi ad after work. 1st Mask oves should b oggles should	ately.	e quantities.	tities			
8.	Hygiene measuresRemove soiled or soaked clorWash hands before breaks anRespiratory protection: DuHand protection: GluEye protection: Gu	thing immedi ad after work. ast Mask oves should b oggles should otton / synthet	ately. De worn when handling bulk o I be worn when handling larg	e quantities.	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance	thing immedi ad after work. ast Mask oves should b oggles should otton / synthet	ately. De worn when handling bulk o I be worn when handling larg	e quantities.	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder	thing immedi ad after work. ast Mask oves should b oggles should otton / synthet operties	ately. be worn when handling bulk o l be worn when handling larg tic overalls should be worn w	e quantities.	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder Colour : Orange, Pink Odour : Peppermint of	thing immedi ad after work. 1st Mask oves should b oggles should otton / synthet operties c, Green, Blue	ately. be worn when handling bulk o l be worn when handling larg tic overalls should be worn w	e quantities.	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder Colour : Orange, Pink Odour : Peppermint of Data relevant to safety	thing immedi ad after work. 1st Mask oves should b oggles should otton / synthet operties c, Green, Blue	ately. be worn when handling bulk of l be worn when handling larg tic overalls should be worn w	e quantities. hen handling large quan	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder Colour : Orange, Pink Odour : Peppermint of	thing immedi ad after work. 1st Mask oves should b oggles should otton / synthet operties c, Green, Blue	ately. be worn when handling bulk o l be worn when handling larg tic overalls should be worn w	e quantities.	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder Colour : Orange, Pink Odour : Peppermint of Data relevant to safety	thing immedi ad after work. 1st Mask oves should b oggles should otton / synthet operties c, Green, Blue	ately. be worn when handling bulk of l be worn when handling larg tic overalls should be worn w	e quantities. hen handling large quan	tities			
	Hygiene measures Remove soiled or soaked clor Wash hands before breaks an Respiratory protection: Du Hand protection: Gl Eye protection: Gd Body protection: Co Physical and chemical pro Appearance Form : Powder Colour : Orange, Pink Odour : Peppermint of Data relevant to safety Flash point :	thing immedi ad after work. 1st Mask oves should b oggles should otton / synthet operties x, Green, Blue or Vanilla	ately. be worn when handling bulk of l be worn when handling larg tic overalls should be worn w e or Yellow Melting Point Range:	e quantities. hen handling large quan	tities			

A:\Alginate Impression Material HSDS.wpd



Product no. 2 500 series &	2 600 series	Version 01/98	S/MW	Status: 01	/98/MW		
Substance code:				Page :	3 (3)		
10. Stability and react	tivity						
Thermal Decomp	osition:						
Stable							
Conditions to Ave		•					
	nditions as material gels	when wet.					
	Toxicological information Possible temporary irritation of the eyes and respiratory mucosa.						
1 0		ated inhalation of dust at hig	gh concen	tration (Silic	cosis)		
12. Ecological informatio		oduct					
There is no ecological	date available for this pro	oduct					
13. Disposal consideration							
	ording to local regulation	ns.					
14. Transport informati	on						
UN No:			DG Class:				
IMO:			kaging Gr	oup:			
IATA:		Packaging Group):				
Correct Technic	cal Name:						
ADR/RID:							
Not regulated for	r transport						
15. Regulatory informa	tion						
Hazard symbols:	20 H C1 11 1	1 6 11 6 1					
		k of irreversible effects through	ugh inhala	ation.			
S phrases: S22:	Do not breathe the dust						
16. Other information	in good faith hairs 1	haad on the latest linelede	a availab		Dontol Co. Ltd		
ũ	5	based on the latest knowledg					
No known relevant informat precaution sheets. The user							
information provided is insu							
Ltd prior to use for further a		in any particular application	i, piease c	ontact P.S.P	.Delital CO.		
and prior to use for further d							
	1						

A:\Alginate Impression Material HSDS.wpd